Results and Current Evaluation from Inspection of Water Intake Power Cable Trench at Fukushima Daiichi Nuclear Power Station Unit 2

July 29, 2013 Tokyo Electric Power Company



Overview of Unit 2 Water Intake Power Cable Trench (1/2)



Overview of Unit 2 Water Intake Power Cable Trench (2/2)





Inspection Results

[Unit 2 A] Unit 2 Seawater pipe trench (Unit 2 vertical shaft A)

Sampling date	Chloride	Cs134	Cs137	All β	H-3
	(ppm)	(Bq/cm³)	(Bq/cm³)	(Bq/cm³)	(Bq/cm³)
May 30, 2013	140	1.8 × 10⁴	3.7 × 10⁴	-	_

[Unit 2 B-1-1] Unit 2 water intake power cable trench (seawater pipe foundation)

Sampling date	Chloride	Cs134	Cs137	ΑΙΙ β	H-3
	(ppm)	(Bq/cm³)	(Bq/cm³)	(Bq/cm³)	(Bq/cm³)
July 26, 2013	8,000	7.5×10⁵	1.6 × 10 ⁶	7.5×10⁵	8.7 × 10 ³

Water level measurement date	Water level*3	Reference: Water level of Unit 2 vertical shaft A*4
July 23, 2013	OP.3150mm	OP.3083mm
July 26, 2013	OP.3150mm	OP.3302mm

[Unit 2 B-2] Unit 2 water intake power cable trench

Sampling date	Chloride	Cs134	Cs137	All β	H-3
	(ppm)	(Bq/cm³)	(Bq/cm³)	(Bq/cm³)	(Bq/cm³)
July 17, 2013	70	1.2×10⁴	2.4×10⁴	2.3 × 104	1.2 × 10 ²

Water level measurement date	Water level ^{*1}	Reference: Water level of Unit 2 vertical shaft A ^{*2}
July 17, 2013	OP.2760mm (water depth: approx. 70mm)	OP.3196mm

*1: Provisional measurement value obtained using a leveling rod.

*3: Value measured using a water level gauge.

*2: Measurement value regularly obtained (data as at 4:00 PM on July 17). *2: Value measured at the same time as the water levels of the cable trench.



Current Evaluation Reflecting Conditions Found in Inspections

Evaluation item	Communication with the Unit 2 seawater pipe trench	Water retained inside the trench
[Unit 2 B-1-1] Unit 2 water intake power cable trench (seawater pipe foundation)	 There seems to be <u>no communication</u> with the seawater pipe trench [Reason] No association has been found between water level changes in this trench and the Unit 2 vertical shaft A. 	 It seems that <u>contaminated water that flowed into</u> <u>the trench immediately after the accident has been</u> <u>retained as it was.</u> [Reasons] The Cs-137 density is in the order of the 6th power of ten (Bq/cm³) as in the case of contaminated water that flowed into the trench immediately after the accident.
[Unit 2 B-2] Unit 2 water intake power cable trench	 There seems to be <u>no communication</u> with the seawater pipe trench [Reason] The trench has a lower water level than the Unit 2 vertical shaft A. 	 The water level has been found unchanged. There is a possibility that water retained there (water depth as of July 19: approx. 7cm) may be residual water since the grout closure immediately after the accident, and <u>the possibility of water having flowed out of the trench is unclear</u>. Rainwater, etc. seems to have flowed into the trench. [Reason] Chloride concentration, cesium densities, etc are low (indicating the possibility of dilution with rainwater)

In order to confirm whether water has flowed out of the trench, measurement of water levels (confirmation of increases and decreases of water levels) is needed.



< Reference > [Unit 2 B-2] Conditions of Water Intake Power Cable Trench Interior (Illustration)



< Reference > [Unit 2 B1-1] Conditions of Water Intake Power Cable Trench (Seawater Pipe Foundation)



* These photos have already been made public since July 19.