


Leakage from the Desalination System (RO3) at Fukushima Daiichi Nuclear Power Station


<Reference>
June 21, 2013
Tokyo Electric Power Company

- Date and Time: Around 2:58 AM on June 21, 2013
- Location: In the temporary warehouse of the desalination system (RO3)
- Outline
 1. At 2:58 AM, a cooperative company worker found a leak detector of the desalination system operating.
 2. At 3:03 AM, a cooperative company worker suspended the desalination system (RO3) and closed the exit valve of the ultra filter raw water pump.
 3. At 3:17 AM, stop of the leakage was confirmed at the site.
 4. From around 4:00 AM to around 6:00 AM, an absorber was placed on the floor.
 5. From around 10:30 AM to around 3:00 PM, collection of remained water was performed in order to secure workability at the site.
 6. At around 1:10 PM, the exit valve was opened to identify the leakage location. We found that the leakage occurred through a cap section in the lower part of a flow meter at the ultra filter raw water pump outlet.
 7. At around 3:00 PM, the flow meter was replaced to a new one.
- Estimated leakage amount: Approx. 250 liters
- Nuclide analysis results
 - Cs134: $5.7 \times 10^{-1} \text{Bq/cm}^3$, Cs137: $1.7 \times 10^0 \text{Bq/cm}^3$
 - All β : $2.6 \times 10^4 \text{Bq/cm}^3$
- Estimated cause: The cap section in the lower part of the flow meter was removed when the ultra filter was cleaned on June 20. The cause of the leakage is estimated to be cracks occurred at the neck part of the cap because the cap was tightened too much after the cleaning.
- Countermeasure: The flow meter will be replaced to a new one if it is found to be contaminated.


Overview of the Desalination System




Overview of the Desalination System (RO3)



Leakage Situation in the Temporary Warehouse of the Desalination System (RO3)



 : leaked area (250m²)

Estimated leakage amount: 250 liters
($\approx 250\text{m}^2 \times \text{depth } 1\text{mm}$)

Leak detector


Leakage Location

Flow meter at the ultra filter
raw water pump outlet

Leakage Location of the Flow Meter (Cap Section in the Lower Part)




Identifying work of the leakage location



Before the identifying work of the leakage location



New flow meter



After the cap section in the lower part of the flow meter was removed (neck part of the cap was damaged)

Estimated Leakage Mechanism

The cap section in the lower part of the flow meter was removed when the ultra filter was cleaned on June 20. The cause of the leakage is estimated to be cracks occurred at the neck part of the cap because the cap was tightened too much after the cleaning.

(No leakage was found at a leakage check utilizing pump operating pressure after the restoration work. Sealing performance of the flow meter is estimated to be maintained by the O rings at that moment.)

