


Inspection Results of the Batch Treatment Tank 2A of Multi-nuclide Removal Equipment (ALPS) in Fukushima Daiichi Nuclear Power Station

<Reference>
July 2, 2013

Tokyo Electric Power Company

■ The bottom part of the batch treatment tank 2A, where penetrant testing (PT) was performed before, was cut in order to have a check.






Inspection Results of the Batch Treatment Tank 2A of Multi-nuclide Removal Equipment (ALPS)

- Parts at which penetration defects were estimated to be located by external surface penetrant testing at the batch treatment tank 2A was cut in order to have a check (1) (vertical welding line ①-2 at the conical part, approx. 70 cm from the lower edge).



Parts at which penetration defect were estimated to be located by external surface penetrant testing (1)



↑ Cut length: 2.60mm

← Cut length: 2.40mm



Some defects were found vanishing, by a gradual cutting. However, bag-like defect was also found, which was gradually widening.

Inspection Results of the Batch Treatment Tank 2A of Multi-nuclide Removal Equipment (ALPS)

- Parts at which penetration defects were estimated to be located by external surface penetrant testing at the batch treatment tank 2A was cut in order to have a check (2) (vertical welding line ①-2 at the conical part, approx. 100 cm from the lower edge).



Parts at which penetration defect were estimated to be located by external surface penetrant testing (2)





↑ Cut length: 2.40mm

← Cut length: 1.70mm

Some defects were found vanishing, by a gradual cutting. However, bag-like defect was also found, which was gradually widening.


Inspection Results of the Batch Treatment Tank 2A of Multi-nuclide Removal Equipment (ALPS)

- Major parts at which penetration defects were estimated to be located by internal surface penetrant testing at the batch treatment tank 2A was cut in order to have a check (2) (welding line ② around the conical part).



↑ Cut length: 2.80mm

← Cut length: 0.13mm



Bag-like defect was found, which was gradually widening, by a gradual cutting.