
Revised Version: "Schedule" written in Page 2 has been corrected on April 19.

Work Performed Today (April 17) in Response to the Leakage from the Underground Reservoirs Tokyo Electric Power Company

Cause Investigation of the Leakage

- Outline
 - Visually inspect the conditions of the impermeable sheet and the leakage detection hole in the leakage detection hole penetration in the northeast side of the underground reservoir No. 2 where the leakage is suspected.
- Work performed today
 - Restoration work of the leakage detection hole penetration The soil covering is scheduled



Photos of the work performed today



Schedule


Itam	April											
ltem	8	9	10	11	12	13	14	15	16	17	18	19
Investigation of the underground reservoir No.2												

■: Planned schedule, ■: Actual schedule

Measures to Prevent the Expansion of Contaminated Water Leakage from the Underground Reservoirs

Outline

 In order to prevent the leaked water in the leakage detection holes from leaking into the ground in the surrounding area, the water in the leakage detection holes will be returned to the underground reservoirs.



Schedule

: Detection holes with high radioactive material densities

Under ground reservoir	Leakage Detection holes	Apr 10 (Wed)	Apr 11 (Thu)	Apr 12 (Fri)	Apr 13 (Sat)	Apr 14 (Sun)	Apr 15 (Mon)	Apr 16 (Tue)	Apr 17 (Wed)
No. 1	Northeast side								
	Southwest side								
No. 2	Northeast side								
	Southwest side								
No. 3	Northeast								*
	side								
	Southwest								
	side								

*Water transfer was conducted since radioactive material density of the water in the detection hole is increasing.

■ Photo of the work performed today



Installation of the pump at underground reservoir No. iii (photo taken on April 13)


[Revision]

T the schedule for April 15 has been corrected as follows.

Southwest side of the underground reservoir

No.1: corrected to "no work performed"





Monitoring of the Impact of the Leakage on the Surrounding Environment (2): Underground Water Monitoring Result (Existing Observation Holes)

