Failure on a Charger Panel of the Air-cooled Gas Turbine Generator Vehicle (No.1) Due to Entrance of a Small Animal Tokyo Electric Power Company Fukushima Daini Nuclear Power Station



Air-cooled gas turbine generator vehicle (No.1) (Near side: generator vehicle, far side: control vehicle)





Contact condition of a small animal and the device (enlarged view)



After implementation of measures to prevent the entry of small animals

