

Area II

Coating done in 2012



The thickness of the coating is planned to be checked through bathymetry. And based on the data taken, additional coating will be performed to strengthen durability if necessary.

slugs exist, only Covering material B was applied.



Coating done in 2012

The figure shown at the "Amount of concrete" is provisional and is subjected to change.

Area I

<Reference> Area with the coating done in front of the water intake.

(On the side of Unit 1 to 4) Coating area: Approx. 34,000m<sup>2</sup>/ Construction period: 2012.3.14 to 5.11. (On the side of Unit 5 & 6) Coating area: Approx. 38,600m<sup>2</sup> / Construction period: 2012.5.16 to 7.05.



<sup>\*</sup> Open ditch of water intake has sea slugs, therefore, covering material with bentonite slurry was applied to make it duplex coating.