Reference Picture 1 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station" Tokyo Electric Power Company June 20, 2011



Used as power source for instrument (page 3)

Taken by : Tokyo Electric Power Company

Reference Picture 2 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Reading instrument by relying on light (page 3)

Taken by : Tokyo Electric Power Company

Reference Picture 3 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Cave-in road (page 4, 11)

Taken by : Tokyo Electric Power Company

Reference Picture 4 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Self-air-set (page 5)

Taken by : Tokyo Electric Power Company

Reference Picture 5 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Flowed tanks by tsunami (page 11)

Taken by : Tokyo Electric Power Company

Reference Picture 6 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Water injection by fire trucks (page 12)

Taken by : Tokyo Electric Power Company

Reference Picture 7 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Explosion at the reactor building of Unit 1. (page 13)

Taken by : Tokyo Electric Power Company

Reference Picture 8 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Devastated status at the Administration Office Building (page 14)

Taken by : Tokyo Electric Power Company

Reference Picture 9 "Initial response at the time of and after the Tohoku-Chihou-Taiheiyo-Oki Earthquake at Fukushima Daiichi Nuclear Power Station"

Tokyo Electric Power Company June 20, 2011



Apparent condition of Unit 3 after explosion (page 35)

Taken by : Tokyo Electric Power Company