

Water Leakage Found Near Units 5-6 Low Radioactivity Density Accumulated

Water Tank at Fukushima Daiichi Nuclear Power Station


Date and Time the leakage was found
December 25, 2012 at around 11:04 AM

Location
Units 5-6 low radioactivity density accumulated water tank area


Outline
A TEPCO employee found water leakage from the sampling pipe outlet near Units 5-6 low radioactivity density accumulated water tank (located outside). Though the leaked water has been absorbed into the ground (gravel) and affected 1m x 1m area, it has not flowed outside since there is no drainage in the surrounding area. The amount of leaked water is estimated to be approx. 10L (max.).

Radioactivity density analysis result
All radioactivity density: $4.3 \times 10^{-1} \text{Bq/cm}^3$
<Reference> Water sampled from Units 5-6 accumulated water tank on October 3: $6.6 \times 10^{-1} \text{Bq/cm}^3$

Map of Fukushima Daiichi Nuclear Power Station



Location where water leakage occurred



[Area surrounding the leakage location]



[Leakage location (Enlarged)]

