


Outline drawing of water removal work on Cesium adsorption tower (vessel) for water treatment facility



It should have been removed at "valve-close" though the hose had been removed at "valve-open", that caused water spewing out from connecting part and got the worker wet.