

## List of motion pictures

~ List of motion pictures that were recorded during March 11 and September 30 by TEPCO at Fukushima Daiichi Nuclear Power Station and that were confirmed at this time not to be published ~

As of November 11, 2011  
Tokyo Electric Power Company

Pushed on TEPCO's web site (until the end of December, 2011) and nuclear information site

Date of record	Recorded task	Recorded place	Time(min, sec)	Issued date	Comments
May 26, 2011	Damage 1 and 2 by Tsunami	Outside of Unit 5 and 6	0:36	Nov 11, 2011	Similar motion pictures have been published on TEPCO web site on September 9 and 24.
August 10, 2011	Installation status of secondary piping of spent fuel pool alternative cooling system	Unit 1; west side of 1st floor of R/B and northwest stairs (1st to 3rd floor), west side of 3rd floor and SFP alternative cooling system, such as secondary piping, heat exchanger and primary pump	7:06		SFP; Spent Fuel Pool
	(after inserviced)				Relative motion picture has been published on TEPCO web site on June 15, 1st floor of Unit 3.
August 23, 2011	Motion picture about the change of injection point of Unit 3 reactor	Unit 3	19:10		Pictures have been published on TEPCO web site on July 27
September 2, 2011	Field inspection of core spray injection on Unit 2	Unit 2	11:26	The second inspection since June 21, 2011	

(1)

Date of Record	Recorded task	Recorded place	Time(min, sec)	Issued date	Comments
March 24, 2011	Water discharge work in spent fuel pool	Unit 4 operating floor	2:10	Nov 11, 2011	Related or similar motive has been published on TEPCO Web site
April 18, 2011	Status check and water discharge work spent fuel pool 1 2	Unit 3 operating floor	51:24		
April 28, 2011	Installation work of water level gauge for thermocouple spent fuel pool	Unit 4 operating floor	0:47		
April 29, 2011	Water level measurement work spent fuel pool 1	Unit 4 SFP pool	4:10		
April 30, 2011	Water level measurement work spent fuel pool 2	Unit 4 SFP pool	8:22		
May 1, 2011	Water level measurement work spent fuel pool 3	Unit 4 SFP pool	15:16		
May 2, 2011	Water sampling work spent fuel pool	Unit 4 operating floor	19:31		
May 3, 2011	Water level measurement work spent fuel pool 4	Unit 4 SFP pool	12:35		
May 4, 2011	Water level measurement work spent fuel pool 5	Unit 4 SFP pool	17:59		
May 6, 2011	Installation work of water level gauge for thermocouple spent fuel pool 2	Unit 4 operating floor	4:55		
May 7, 2011	Status of operating floor including spent fuel pool 1 2 3	Unit 4 operating floor	51:31		

(2)

Date of Record	Recorded task	Recorded place	Time(min, sec)	Issued date	Comments
May 15, 2011	Status of operating floor including spent fuel pool	Unit 4 operating floor	10:46	Nov 11, 2011	Related or similar motive has been published on TEPCO Web site
May 16, 2011	Status of operating floor including spent fuel pool 1 2 3	Unit 1 operatinf floor	45:03		
May 20, 2011	Water discharge work on debris operating floor	Unit 1 operatinf floor	3:26		
June 8, 2011	Spray work of dust inhibitor R/B operating floor and on the wall	Unit 1 wall	10:01		
June 9, 2011	Spray work of dust inhibitor R/B operating floor and on the wall	Unit 3	20:00		

**\* Relative or similar motion pictures of above ones (published on TEPCO's Web site)**

- Mar 17, 2011 Airborne Imagery
- Mar 22, 2011 Water disdcharge work for Unit 4
- Mar 24, 2011 Water disdcharge work for Unit 4
- Apr 10, 2011 Airborne Imagery for Unit 3 and 4
- Apr 15, 2011 Airborne Imagery for Unit 1, 3 and 4
- Apr 12, 2011 Sampling of SFP, Unit 4
- May 8, 2011 Under water of SFP, Unit 4
- May 8, 2011 Under water of SFP, Unit 3
- May 28, 2011 Spray work of dust inhibitor, Unit 1 T/B
- Jun 1, 2011 Spray work of dust inhibitor, Unit 2 R/B

Published on TEPCO's web site (until the end of December, 2011) and nuclear information site

Date of Record	Recorded task	Recorded place	Time(min, sec)	Issued date	Comments
Apr 2, 2011	Status of water leakage on pure water tank No.2 1 2		0:56	Nov 11, 2011	
Apr 3 2011	Status of water leakage on pure water tank No.2 3 4		0:54		
Apr 4 2011	Status of water leakage on pure water tank No.3		0:44		
Apr 5 2011	Status of water leakage on pure water tank No.2		1:07		
Apr 6 2011	Status of water leakage on pure water tank No.2 1 2		1:21		
Apr 7 2011	Status of water leakage on pure water tank No.3		0:48		Recorded during the patrol for accumulated water. FSTR ;
Apr 8 2011	Water leakage in Unit 6 ESWGR room 1 2		3:02		Recorded during the patrol for accumulated water. ESWGR ; Emergency Electrical Equipment Room
Apr 9 2011	Water leakage on the wall of Unit 6 ESWGR room		0:28		Recorded during the patrol for accumulated water
Apr 10 2011	Clack and water leakage on the wall of Unit 6 RHR room (A)		1:27		Recorded during the patrol for accumulated water. RHR ; Residual Heat Removal system
Apr 11 2011	Puddle in Unit 6 extubation area 1 2		1:52		Recorded during the patrol for accumulated water
Apr 12 2011	Status of inflow in Unit 5 CS (B) room		1:59		Recorded during the patrol for accumulated water
Apr 13 2011	Storm funnel on the 2nd floor of Unit 5 T/B 1 2		0:59		Recorded during the patrol for accumulated water
Apr 14 2011	Accumulated water at Unit 6 HPCS system diesel generator trench		1:02		Recorded during the patrol for accumulated water. HPCS ; High Pressure Core Spray
Apr 15 2011	Accumulated water at Unit 6 RCIC room		0:34		Recorded during the patrol for accumulated water. RCIC ; Reactor Core Isolation Cooling system
Apr 16 2011	Accumulated water at the front of Unit 6 residual heat removal system room (A) room		1:15		Recorded during the patrol for accumulated water
Apr 17 2011	Status of underground water inflow at path-through slot of Unit 5 CS (B) pump room		0:54		Recorded during the patrol for accumulated water
Apr 18 2011	Sea water hose of Unit 5 temporary RHRS system		1:24		Commissioning of pump RHRS; Residual Heat Removal Sea water system
Apr 19 2011	Water flood on the underground floor of Unit 6 T/B between TB and MC		1:05		Recorded during the patrol for accumulated water
Apr 20 2011	Water flood on the underground floor of Unit 6 T/B "Bamboo Corridor"		0:18		Recorded during the patrol for accumulated water
Apr 21 2011	Water flood at Unit 6 heater drain pump --- circuit breaker room		0:46		Recorded during the patrol for accumulated water
Apr 22 2011	In front of Unit 3,4 S/B underground floor cable bolt room 1		0:30		Recorded during the patrol for accumulated water
Apr 23 2011	In front of Unit 3,4 S/B underground floor cable bolt room 2 3		0:43		Recorded during the patrol for accumulated water
Apr 24 2011	Water leakage point in Unit 3,4 S/B underground floor cable bolt room		0:40		Recorded during the patrol for accumulated water
Apr 25 2011	Water flood in Unit 6 circuit breaker room		1:28		Recorded during the patrol for accumulated water
Apr 26 2011	Underground water inflow at Unit 6 RW trench 1 2 3 4 5 6 7		3:06		Recorded during the patrol for accumulated water
Apr 27 2011	Unit 6 leakage in FSTR passage in the trench just in the trench.avi		2:47		Recorded during the patrol for accumulated water FSTR; Filter Sludge Tank Room

Published on TEPCO's web site (until the end of December, 2011) and nuclear information site

Date of Record	Recorded task	Recorded place	Time(min, sec)	Issued date	Comments
Sep 2, 2011	Leakage of trench rubber boots of high pressure core spray system diesel generator room		4:35	Nov 11, 2011	Recorded during the patrol for accumulated water Rubber boots; connection of pipes made by rubber
Sep 3, 2011	After alarm of leakage annunciator (alarm indicator) of trench rubber boots of high pressure core spray system diesel generator room		1:13		Recorded during the patrol for accumulated water
Sep 21, 2011	Leakage of rain by typhoon No.15	Cable tray in the south side of Unit 5 HPCP (C)	0:39		Recorded during the patrol for accumulated water HPCP; High Pressure Condensed water Pump
Sep 21, 2011	Leakage of rain by typhoon No.15	The back of Unit 5 (Primary Containment Vessel) HVH 5-30A	0:42		Recorded during the patrol for accumulated water HVH; Heating Ventilating Handling system
Sep 21, 2011	Leakage of rain by typhoon No.15	Unit 6 ESWGR (5)	0:17		Recorded during the patrol for accumulated water E; Emergency
Sep 21, 2011	Leakage of rain by typhoon No.15	Unit 6 SWGR as of 22:00	0:42		Recorded during the patrol for accumulated water SWGR; Switch Geer
Sep 21, 2011	Leakage of rain by typhoon No.15	Unit 6 SWGR as of 23:00	0:37		Recorded during the patrol for accumulated water
Sep 22, 2011	Leakage of rain by typhoon No.15	Unit 6 access way between SWGR and T/B	1:41		Recorded during the patrol for accumulated water
Sep 22, 2011	Leakage of rain by typhoon No.15	Dripping status at Unit 6 turbine operating floor 1 2	0:43		Recorded during the patrol for accumulated water
Sep 22, 2011	Leakage of rain by typhoon No.15	Water flood on Unit 6 condensed water demineraliser regenerator room 1 2 3 4	1:17		Recorded during the patrol for accumulated water
Sep 22, 2011	Leakage of rain by typhoon No.15	Rubber boots on Unit 6 condensed water demineraliser regenerator room	0:40		Pictures
Sep 22, 2011	Leakage of rain by typhoon No.15	Water leakage at Unit 6 Tb --- circuit breaker room	2:42		Recorded during the patrol for accumulated water
Sep 22, 2011	Typhoon No.15	Unit 5 high pressure condensed water pump hill side 1 2	0:36		Recorded during the patrol for accumulated water
Sep 22, 2011	Typhoon No.15	Around lavatory on the underground of Unit 5 T/B	0:09		Recorded during the patrol for accumulated water
Sep 22, 2011	Typhoon No.15	Unit 5 house transformer room south hill side	0:20		Recorded during the patrol for accumulated water HTR; House Transformer Room
Sep 22, 2011	Typhoon No.15	Wate leakage on Unit 6 circuit breaker room	0:19		Recorded during the patrol for accumulated water
Sep 26, 2011	Water leakage status of Unit 6 HVE (A).avi		0:26	Recorded during the patrol for accumulated water HVE; Heating Ventilating Exhausted system	