



The Water Leakage at the Accumulated Water Transferring Pipe in Unit 3 Turbine Building at Fukushima Daiichi Nuclear Power Station

■ The location of water leakage, Unit 3 Turbine Building (system diagram)





— Pressure hose



Area affected by the water leakage
3m x 6m x 5mm

Amount of the leaked water
90 litre

Results of the leaked water nuclide analysis
I-131: ND
Cs-134 : 1.0×10^4 Bq/cm³
Cs-137 : 1.8×10^4 Bq/cm³

10/15 Location of water leakage

8/14 Location of water leakage

Location of water leakage

Difference in level
(approx. 1m)

Unit 4 Turbine Building

Unit 3 Turbine Building large equipment hatch

Unit 3 Turbine Building

Service building

Valve unit