



Assumed cause

**< Assumed cause >**  
• Water flowed due to filled with water at crushed stone point installed at the bottom of trench



# Tentative planned countermeasure construction



**A-A Section view**

**Plain view**