

# Conditions of the bank protection area at Fukushima Daiichi Nuclear Power Station

Reference  
September 21, 2016  
Tokyo Electric Power Company Holdings, Inc.

## Summary

Time and date

September 20, 2016 from 10 p.m. to 11 p.m.



No deformation found on the north side of the Seaside Impermeable Wall



No water flowing out of the observation well B for the groundwater drain system

Photos taken by: Tokyo Electric Power Company Holdings, Inc.

Photos taken on: September 20, 2016