Attachment 2

## <Compensation for household goods in houses damaged by the earthquake or Tsunami>

| Tsunami>        |  |  |
|-----------------|--|--|
| Degree of       | Damage state of the house  | Compensation amount  |
| damage          | [Examples of earthquake damage by house structure]   | ratio  |
| Collapse        | <ul> <li>A case where the house was collapsed by the earthquake</li> <li>A case where the house was carried away by Tsunami</li> <li>For houses that collapse or loss is confirmed by satellite photo, etc., the houses are considered as collapsed.</li> </ul>  | 20% of the compensation<br>amount calculated based on<br>the number of family<br>members and family<br>structure in the zone where<br>residents cannot return for a<br>long time |
| Total loss      | <ul> <li>A state where the house is structurally destroyed<br/>and residents cannot continue to live</li> <li>Due to Tsunami, a half height or more of the house<br/>was flooded [Wooden structure] Destruction of a half or more of pillars or basement, or<br/>tilt of house that can be felt [Steel frame structure] Tilt of house that can be felt, or fall of a half or more of<br/>external walls [Reinforced concrete structure] Tilt of house that can be felt, or loss with which steel<br/>frames of a half or more of pillars or beams can be seen<br/>on floors severely damaged</li> </ul>      | 100%   |
| Half loss       | <ul> <li>A state where the house is structurally destroyed and residents cannot continue to live without extensive repair</li> <li>Due to Tsunami, 1 m or more above the floor of the house was flooded [Wooden structure] Tilt of pillars or tilt of walls with which some rooms cannot be used [Steel frame structure] Cracks or joint opening of external wall material with a half or more of external walls [Reinforced concrete structure] Cracks of 40% or more pillars and beams with which steel frames can be seen on floors severely damaged</li> </ul>   | 100%   |
| Partial<br>loss | <ul> <li>A state where the house is not structurally destroyed much and can be recovered with relatively small repair</li> <li>Due to Tsunami, the house was flooded above the floor <ul> <li>[Wooden structure]</li> <li>Damage that requires repair for pillars, basement, roof, external walls, etc.</li> <li>[Steel frame structure]</li> <li>Difficulty in open/ close for a part of openings. Visible cracks or joint distortion of external walls</li> <li>[Reinforced concrete structure]</li> <li>Visible cracks of 20% or more pillars and beams on floors severely damaged</li> </ul> </li> </ul> | 100%   |