

Results of the Local Vacuum Test for the Tank Bottom Plate

- We conducted the local vacuum test at the point(s) in which 1) bubbles were vacuumed up in the vacuum test for the bottom-plate, 2) bolts were found loose, and 3) swelling of sealing was found. As a result, **we found foaming at the point 1)**, but NO foaming at the points 2) and 3).

