

Table 10 Cumulative Exposure Dose Data of Subsequent Month(s) After March 2011

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Max. (mSv) | Ave. (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------|------------|
| 201103-201103 | TEPCO | 40 | 66 | 239 | 529 | 539 | 119 | 77 | 65 | 16 | 0 | 6 | 1696 | 670.36 | 31.53 |
| | Contractors | 405 | 524 | 397 | 460 | 371 | 65 | 34 | 17 | 2 | 2 | 0 | 2277 | 238.42 | 14.16 |
| | Total | 445 | 590 | 636 | 989 | 910 | 184 | 111 | 82 | 18 | 2 | 6 | 3973 | 670.36 | 21.57 |
| 201103-201104 | TEPCO | 196 | 288 | 350 | 479 | 623 | 170 | 79 | 95 | 19 | 1 | 6 | 2306 | 678.08 | 27.97 |
| | Contractors | 1460 | 1555 | 765 | 709 | 568 | 95 | 42 | 18 | 2 | 2 | 0 | 5216 | 238.42 | 9.69 |
| | Total | 1656 | 1843 | 1115 | 1188 | 1191 | 265 | 121 | 113 | 21 | 3 | 6 | 7522 | 678.08 | 15.29 |
| 201103-201105 | TEPCO | 312 | 404 | 354 | 489 | 637 | 190 | 95 | 101 | 20 | 1 | 6 | 2609 | 678.80 | 26.50 |
| | Contractors | 2253 | 2515 | 1219 | 1079 | 777 | 121 | 47 | 20 | 2 | 2 | 0 | 8035 | 238.42 | 8.73 |
| | Total | 2565 | 2919 | 1573 | 1568 | 1414 | 311 | 142 | 121 | 22 | 3 | 6 | 10644 | 678.80 | 13.08 |
| 201103-201106 | TEPCO | 399 | 444 | 364 | 498 | 647 | 185 | 112 | 105 | 22 | 1 | 6 | 2783 | 678.80 | 25.87 |
| | Contractors | 2681 | 2985 | 1540 | 1475 | 1077 | 135 | 50 | 20 | 2 | 2 | 0 | 9967 | 238.42 | 9.01 |
| | Total | 3080 | 3429 | 1904 | 1973 | 1724 | 320 | 162 | 125 | 24 | 3 | 6 | 12750 | 678.80 | 12.69 |
| 201103-201107 | TEPCO | 521 | 482 | 362 | 498 | 655 | 186 | 122 | 109 | 22 | 1 | 6 | 2964 | 678.80 | 25.06 |
| | Contractors | 3059 | 3656 | 1867 | 1746 | 1282 | 158 | 52 | 20 | 2 | 2 | 0 | 11844 | 238.42 | 8.92 |
| | Total | 3580 | 4138 | 2229 | 2244 | 1937 | 344 | 174 | 129 | 24 | 3 | 6 | 14808 | 678.80 | 12.15 |
| 201103-201108 | TEPCO | 565 | 505 | 358 | 495 | 659 | 201 | 125 | 115 | 22 | 1 | 6 | 3052 | 678.80 | 25.06 |
| | Contractors | 3122 | 3834 | 2178 | 1978 | 1521 | 170 | 53 | 20 | 2 | 2 | 0 | 12880 | 238.42 | 9.26 |
| | Total | 3687 | 4339 | 2536 | 2473 | 2180 | 371 | 178 | 135 | 24 | 3 | 6 | 15932 | 678.80 | 12.29 |
| 201103-201109 | TEPCO | 604 | 496 | 363 | 494 | 654 | 214 | 132 | 117 | 24 | 1 | 6 | 3105 | 678.80 | 25.20 |
| | Contractors | 3296 | 4013 | 2274 | 2267 | 1693 | 187 | 57 | 20 | 2 | 2 | 0 | 13811 | 238.42 | 9.51 |
| | Total | 3900 | 4509 | 2637 | 2761 | 2347 | 401 | 189 | 137 | 26 | 3 | 6 | 16916 | 678.80 | 12.39 |
| 201103-201110 | TEPCO | 627 | 511 | 355 | 490 | 651 | 226 | 144 | 116 | 26 | 1 | 6 | 3153 | 678.80 | 25.40 |
| | Contractors | 3512 | 4102 | 2359 | 2455 | 1860 | 219 | 58 | 20 | 2 | 2 | 0 | 14589 | 238.42 | 9.72 |
| | Total | 4139 | 4613 | 2714 | 2945 | 2511 | 445 | 202 | 136 | 28 | 3 | 6 | 17742 | 678.80 | 12.50 |
| 201103-201111 | TEPCO | 656 | 543 | 350 | 486 | 654 | 229 | 152 | 116 | 26 | 1 | 6 | 3219 | 678.80 | 25.27 |
| | Contractors | 4063 | 4228 | 2366 | 2584 | 2034 | 231 | 62 | 20 | 2 | 2 | 0 | 15592 | 238.42 | 9.61 |
| | Total | 4719 | 4771 | 2716 | 3070 | 2688 | 460 | 214 | 136 | 28 | 3 | 6 | 18811 | 678.80 | 12.29 |
| 201103-201112 | TEPCO | 687 | 557 | 354 | 487 | 647 | 240 | 161 | 116 | 26 | 1 | 6 | 3282 | 678.80 | 25.19 |
| | Contractors | 4237 | 4398 | 2430 | 2717 | 2172 | 238 | 62 | 20 | 2 | 2 | 0 | 16278 | 238.42 | 9.68 |
| | Total | 4924 | 4955 | 2784 | 3204 | 2819 | 478 | 223 | 136 | 28 | 3 | 6 | 19560 | 678.80 | 12.29 |
| 201103-201201 | TEPCO | 698 | 575 | 366 | 485 | 643 | 241 | 173 | 116 | 26 | 1 | 6 | 3330 | 678.80 | 25.21 |
| | Contractors | 4416 | 4525 | 2461 | 2785 | 2323 | 243 | 62 | 20 | 2 | 2 | 0 | 16839 | 238.42 | 9.76 |
| | Total | 5114 | 5100 | 2827 | 3270 | 2966 | 484 | 235 | 136 | 28 | 3 | 6 | 20169 | 678.80 | 12.31 |
| 201103-201202 | TEPCO | 705 | 590 | 374 | 490 | 639 | 246 | 178 | 116 | 26 | 1 | 6 | 3371 | 678.80 | 25.21 |
| | Contractors | 4449 | 4588 | 2523 | 2826 | 2509 | 248 | 64 | 20 | 2 | 2 | 0 | 17231 | 238.42 | 9.96 |
| | Total | 5154 | 5178 | 2897 | 3316 | 3148 | 494 | 242 | 136 | 28 | 3 | 6 | 20602 | 678.80 | 12.46 |
| 201103-201203 | TEPCO | 735 | 589 | 377 | 491 | 630 | 257 | 186 | 117 | 26 | 1 | 6 | 3415 | 678.80 | 25.15 |
| | Contractors | 4632 | 4621 | 2557 | 2892 | 2660 | 258 | 65 | 20 | 2 | 2 | 0 | 17709 | 238.42 | 10.06 |
| | Total | 5367 | 5210 | 2934 | 3383 | 3290 | 515 | 251 | 137 | 28 | 3 | 6 | 21124 | 678.80 | 12.50 |
| 201103-201204 | TEPCO | 753 | 591 | 374 | 505 | 623 | 259 | 195 | 117 | 26 | 1 | 6 | 3450 | 678.80 | 25.13 |
| | Contractors | 4955 | 4707 | 2554 | 2952 | 2756 | 277 | 65 | 20 | 2 | 2 | 0 | 18290 | 238.42 | 10.05 |
| | Total | 5708 | 5298 | 2928 | 3457 | 3379 | 536 | 260 | 137 | 28 | 3 | 6 | 21740 | 678.80 | 12.44 |
| 201103-201205 | TEPCO | 771 | 594 | 377 | 500 | 624 | 262 | 201 | 117 | 26 | 1 | 6 | 3479 | 678.80 | 25.12 |
| | Contractors | 5246 | 4828 | 2600 | 2955 | 2856 | 313 | 66 | 20 | 2 | 2 | 0 | 18888 | 238.42 | 10.07 |
| | Total | 6017 | 5422 | 2977 | 3455 | 3480 | 575 | 267 | 137 | 28 | 3 | 6 | 22367 | 678.80 | 12.41 |
| 201103-201206 | TEPCO | 778 | 598 | 383 | 500 | 621 | 268 | 206 | 117 | 26 | 1 | 6 | 3504 | 678.80 | 25.17 |
| | Contractors | 5322 | 5130 | 2635 | 2998 | 2930 | 348 | 69 | 20 | 2 | 2 | 0 | 19456 | 238.42 | 10.11 |
| | Total | 6100 | 5728 | 3018 | 3498 | 3551 | 616 | 275 | 137 | 28 | 3 | 6 | 22960 | 678.80 | 12.41 |
| 201103-201207 | TEPCO | 813 | 602 | 384 | 502 | 622 | 266 | 213 | 117 | 26 | 1 | 6 | 3552 | 678.80 | 25.00 |
| | Contractors | 5381 | 5302 | 2682 | 3047 | 3021 | 390 | 70 | 20 | 2 | 2 | 0 | 19917 | 238.42 | 10.21 |
| | Total | 6194 | 5904 | 3066 | 3549 | 3643 | 656 | 283 | 137 | 28 | 3 | 6 | 23469 | 678.80 | 12.45 |
| 201103-201208 | TEPCO | 825 | 612 | 387 | 502 | 616 | 277 | 213 | 117 | 26 | 1 | 6 | 3582 | 678.80 | 24.96 |
| | Contractors | 5507 | 5400 | 2728 | 3079 | 3087 | 410 | 73 | 20 | 2 | 2 | 0 | 20308 | 238.42 | 10.26 |
| | Total | 6332 | 6012 | 3115 | 3581 | 3703 | 687 | 286 | 137 | 28 | 3 | 6 | 23890 | 678.80 | 12.46 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Max. (mSv) | Ave. (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------|------------|
| 201103-201209 | TEPCO | 812 | 621 | 391 | 502 | 614 | 281 | 218 | 117 | 26 | 1 | 6 | 3589 | 678.80 | 25.07 |
| | Contractors | 5572 | 5503 | 2833 | 3082 | 3174 | 437 | 73 | 20 | 2 | 2 | 0 | 20698 | 238.42 | 10.33 |
| | Total | 6384 | 6124 | 3224 | 3584 | 3788 | 718 | 291 | 137 | 28 | 3 | 6 | 24287 | 678.80 | 12.51 |
| 201103-201210 | TEPCO | 841 | 630 | 392 | 501 | 616 | 288 | 220 | 117 | 26 | 1 | 6 | 3638 | 678.80 | 24.90 |
| | Contractors | 5697 | 5597 | 2947 | 3140 | 3223 | 457 | 76 | 20 | 2 | 2 | 0 | 21161 | 238.42 | 10.35 |
| | Total | 6538 | 6227 | 3339 | 3641 | 3839 | 745 | 296 | 137 | 28 | 3 | 6 | 24799 | 678.80 | 12.49 |
| 201103-201211 | TEPCO | 824 | 647 | 395 | 498 | 612 | 294 | 225 | 117 | 26 | 1 | 6 | 3645 | 678.80 | 25.01 |
| | Contractors | 5840 | 5653 | 3018 | 3213 | 3277 | 472 | 80 | 20 | 2 | 2 | 0 | 21577 | 238.42 | 10.39 |
| | Total | 6664 | 6300 | 3413 | 3711 | 3889 | 766 | 305 | 137 | 28 | 3 | 6 | 25222 | 678.80 | 12.50 |
| 201103-201212 | TEPCO | 824 | 642 | 409 | 494 | 612 | 297 | 229 | 117 | 26 | 1 | 6 | 3657 | 678.80 | 25.09 |
| | Contractors | 6014 | 5788 | 3081 | 3254 | 3351 | 495 | 80 | 20 | 2 | 2 | 0 | 22087 | 238.42 | 10.40 |
| | Total | 6838 | 6430 | 3490 | 3748 | 3963 | 792 | 309 | 137 | 28 | 3 | 6 | 25744 | 678.80 | 12.49 |
| 201103-201301 | TEPCO | 824 | 645 | 411 | 495 | 615 | 294 | 234 | 117 | 26 | 1 | 6 | 3668 | 678.80 | 25.13 |
| | Contractors | 6189 | 5869 | 3156 | 3315 | 3422 | 511 | 80 | 20 | 2 | 2 | 0 | 22566 | 238.42 | 10.40 |
| | Total | 7013 | 6514 | 3567 | 3810 | 4037 | 805 | 314 | 137 | 28 | 3 | 6 | 26234 | 678.80 | 12.46 |
| 201103-201302 | TEPCO | 828 | 645 | 413 | 498 | 618 | 295 | 235 | 117 | 26 | 1 | 6 | 3682 | 678.80 | 25.15 |
| | Contractors | 6355 | 5961 | 3168 | 3427 | 3512 | 539 | 83 | 20 | 2 | 2 | 0 | 23069 | 238.42 | 10.47 |
| | Total | 7183 | 6606 | 3581 | 3925 | 4130 | 834 | 318 | 137 | 28 | 3 | 6 | 26751 | 678.80 | 12.49 |
| 201103-201303 | TEPCO | 836 | 639 | 423 | 500 | 617 | 298 | 238 | 117 | 26 | 1 | 6 | 3701 | 678.80 | 25.18 |
| | Contractors | 6510 | 6062 | 3239 | 3502 | 3626 | 570 | 85 | 20 | 2 | 2 | 0 | 23618 | 238.42 | 10.57 |
| | Total | 7346 | 6701 | 3662 | 4002 | 4243 | 868 | 323 | 137 | 28 | 3 | 6 | 27319 | 678.80 | 12.55 |
| 201103-201304 | TEPCO | 874 | 654 | 432 | 501 | 619 | 301 | 239 | 117 | 26 | 1 | 6 | 3770 | 678.80 | 24.86 |
| | Contractors | 6731 | 6156 | 3286 | 3540 | 3682 | 590 | 86 | 20 | 2 | 2 | 0 | 24095 | 238.42 | 10.55 |
| | Total | 7605 | 6810 | 3718 | 4041 | 4301 | 891 | 325 | 137 | 28 | 3 | 6 | 27865 | 678.80 | 12.49 |
| 201103-201305 | TEPCO | 878 | 657 | 433 | 510 | 620 | 300 | 242 | 117 | 26 | 1 | 6 | 3790 | 678.80 | 24.85 |
| | Contractors | 6885 | 6273 | 3293 | 3563 | 3738 | 613 | 87 | 20 | 2 | 2 | 0 | 24476 | 238.42 | 10.57 |
| | Total | 7763 | 6930 | 3726 | 4073 | 4358 | 913 | 329 | 137 | 28 | 3 | 6 | 28266 | 678.80 | 12.48 |
| 201103-201306 | TEPCO | 878 | 661 | 430 | 520 | 618 | 301 | 245 | 117 | 26 | 1 | 6 | 3803 | 678.80 | 24.88 |
| | Contractors | 6962 | 6338 | 3327 | 3558 | 3804 | 644 | 90 | 20 | 2 | 2 | 0 | 24747 | 238.42 | 10.63 |
| | Total | 7840 | 6999 | 3757 | 4078 | 4422 | 945 | 335 | 137 | 28 | 3 | 6 | 28550 | 678.80 | 12.53 |
| 201103-201307 | TEPCO | 910 | 667 | 426 | 531 | 615 | 306 | 245 | 117 | 26 | 1 | 6 | 3850 | 678.80 | 24.68 |
| | Contractors | 7106 | 6402 | 3392 | 3568 | 3838 | 678 | 92 | 20 | 2 | 2 | 0 | 25100 | 238.42 | 10.66 |
| | Total | 8016 | 7069 | 3818 | 4099 | 4453 | 984 | 337 | 137 | 28 | 3 | 6 | 28950 | 678.80 | 12.52 |
| 201103-201308 | TEPCO | 908 | 679 | 425 | 536 | 612 | 311 | 249 | 117 | 26 | 1 | 6 | 3870 | 678.80 | 24.68 |
| | Contractors | 7174 | 6502 | 3431 | 3595 | 3906 | 705 | 97 | 20 | 2 | 2 | 0 | 25434 | 238.42 | 10.72 |
| | Total | 8082 | 7181 | 3856 | 4131 | 4518 | 1016 | 346 | 137 | 28 | 3 | 6 | 29304 | 678.80 | 12.56 |
| 201103-201309 | TEPCO | 978 | 685 | 432 | 539 | 607 | 315 | 252 | 117 | 26 | 1 | 6 | 3958 | 678.80 | 24.24 |
| | Contractors | 7277 | 6519 | 3535 | 3648 | 3982 | 740 | 99 | 20 | 2 | 2 | 0 | 25824 | 238.42 | 10.82 |
| | Total | 8255 | 7204 | 3967 | 4187 | 4589 | 1055 | 351 | 137 | 28 | 3 | 6 | 29782 | 678.80 | 12.60 |
| 201103-201310 | TEPCO | 1018 | 700 | 436 | 540 | 611 | 315 | 257 | 117 | 26 | 1 | 6 | 4027 | 678.80 | 23.97 |
| | Contractors | 7391 | 6629 | 3585 | 3735 | 4075 | 777 | 105 | 20 | 2 | 2 | 0 | 26321 | 238.42 | 10.91 |
| | Total | 8409 | 7329 | 4021 | 4275 | 4686 | 1092 | 362 | 137 | 28 | 3 | 6 | 30348 | 678.80 | 12.64 |
| 201103-201311 | TEPCO | 1014 | 724 | 438 | 542 | 611 | 320 | 258 | 117 | 26 | 1 | 6 | 4057 | 678.80 | 23.92 |
| | Contractors | 7579 | 6701 | 3634 | 3802 | 4142 | 830 | 110 | 20 | 2 | 2 | 0 | 26822 | 238.42 | 10.97 |
| | Total | 8593 | 7425 | 4072 | 4344 | 4753 | 1150 | 368 | 137 | 28 | 3 | 6 | 30879 | 678.80 | 12.67 |
| 201103-201312 | TEPCO | 1013 | 736 | 437 | 546 | 613 | 322 | 259 | 117 | 26 | 1 | 6 | 4076 | 678.80 | 23.93 |
| | Contractors | 7675 | 6822 | 3685 | 3887 | 4212 | 859 | 114 | 20 | 2 | 2 | 0 | 27278 | 238.42 | 11.02 |
| | Total | 8688 | 7558 | 4122 | 4433 | 4825 | 1181 | 373 | 137 | 28 | 3 | 6 | 31354 | 678.80 | 12.70 |
| 201103-201401 | TEPCO | 1005 | 751 | 439 | 548 | 616 | 321 | 262 | 117 | 26 | 1 | 6 | 4092 | 678.80 | 23.93 |
| | Contractors | 7881 | 6957 | 3787 | 3957 | 4308 | 883 | 121 | 20 | 2 | 2 | 0 | 27918 | 238.42 | 11.01 |
| | Total | 8886 | 7708 | 4226 | 4505 | 4924 | 1204 | 383 | 137 | 28 | 3 | 6 | 32010 | 678.80 | 12.67 |
| 201103-201402 | TEPCO | 1013 | 753 | 446 | 547 | 620 | 319 | 265 | 117 | 26 | 1 | 6 | 4113 | 678.80 | 23.90 |
| | Contractors | 8027 | 7083 | 3807 | 4071 | 4382 | 914 | 123 | 20 | 2 | 2 | 0 | 28431 | 238.42 | 11.04 |
| | Total | 9040 | 7836 | 4253 | 4618 | 5002 | 1233 | 388 | 137 | 28 | 3 | 6 | 32544 | 678.80 | 12.67 |
| 201103-201403 | TEPCO | 1015 | 752 | 452 | 553 | 618 | 319 | 269 | 117 | 26 | 1 | 6 | 4128 | 678.80 | 23.91 |
| | Contractors | 8247 | 7248 | 3901 | 4173 | 4457 | 949 | 129 | 20 | 2 | 2 | 0 | 29128 | 238.42 | 11.04 |
| | Total | 9262 | 8000 | 4353 | 4726 | 5075 | 1268 | 398 | 137 | 28 | 3 | 6 | 33256 | 678.80 | 12.64 |
| 201103-201404 | TEPCO | 1025 | 753 | 467 | 558 | 612 | 323 | 273 | 117 | 26 | 1 | 6 | 4161 | 678.80 | 23.82 |
| | Contractors | 8667 | 7475 | 3971 | 4223 | 4563 | 980 | 134 | 20 | 2 | 2 | 0 | 30037 | 238.42 | 10.95 |
| | Total | 9692 | 8228 | 4438 | 4781 | 5175 | 1303 | 407 | 137 | 28 | 3 | 6 | 34198 | 678.80 | 12.52 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Max. (mSv) | Ave. (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------|------------|
| 201103-201405 | TEPCO | 1043 | 760 | 469 | 565 | 613 | 321 | 276 | 117 | 26 | 1 | 6 | 4197 | 678.80 | 23.70 |
| | Contractors | 9076 | 7750 | 4042 | 4276 | 4670 | 1014 | 137 | 20 | 2 | 2 | 0 | 30989 | 238.42 | 10.86 |
| | Total | 10119 | 8510 | 4511 | 4841 | 5283 | 1335 | 413 | 137 | 28 | 3 | 6 | 35186 | 678.80 | 12.39 |
| 201103-201406 | TEPCO | 1050 | 764 | 472 | 566 | 617 | 322 | 278 | 117 | 26 | 1 | 6 | 4219 | 678.80 | 23.66 |
| | Contractors | 9482 | 7928 | 4235 | 4340 | 4752 | 1052 | 145 | 20 | 2 | 2 | 0 | 31958 | 238.42 | 10.80 |
| | Total | 10532 | 8692 | 4707 | 4906 | 5369 | 1374 | 423 | 137 | 28 | 3 | 6 | 36177 | 678.80 | 12.30 |
| 201103-201407 | TEPCO | 1095 | 775 | 469 | 572 | 620 | 321 | 279 | 117 | 26 | 1 | 6 | 4281 | 678.80 | 23.39 |
| | Contractors | 9890 | 8076 | 4298 | 4480 | 4841 | 1079 | 155 | 20 | 2 | 2 | 0 | 32843 | 238.42 | 10.76 |
| | Total | 10985 | 8851 | 4767 | 5052 | 5461 | 1400 | 434 | 137 | 28 | 3 | 6 | 37124 | 678.80 | 12.21 |
| 201103-201408 | TEPCO | 1097 | 783 | 473 | 570 | 623 | 320 | 282 | 117 | 26 | 1 | 6 | 4298 | 678.80 | 23.36 |
| | Contractors | 10123 | 8147 | 4412 | 4535 | 4930 | 1104 | 160 | 20 | 2 | 2 | 0 | 33435 | 238.42 | 10.77 |
| | Total | 11220 | 8930 | 4885 | 5105 | 5553 | 1424 | 442 | 137 | 28 | 3 | 6 | 37733 | 678.80 | 12.20 |
| 201103-201409 | TEPCO | 1107 | 788 | 481 | 570 | 624 | 321 | 283 | 117 | 26 | 1 | 6 | 4324 | 678.80 | 23.29 |
| | Contractors | 10419 | 8282 | 4465 | 4668 | 5051 | 1137 | 163 | 20 | 2 | 2 | 0 | 34209 | 238.42 | 10.77 |
| | Total | 11526 | 9070 | 4946 | 5238 | 5675 | 1458 | 446 | 137 | 28 | 3 | 6 | 38533 | 678.80 | 12.17 |
| 201103-201410 | TEPCO | 1111 | 796 | 484 | 575 | 626 | 322 | 285 | 117 | 26 | 1 | 6 | 4349 | 678.80 | 23.23 |
| | Contractors | 10635 | 8460 | 4523 | 4726 | 5154 | 1180 | 166 | 20 | 2 | 2 | 0 | 34868 | 238.42 | 10.79 |
| | Total | 11746 | 9256 | 5007 | 5301 | 5780 | 1502 | 451 | 137 | 28 | 3 | 6 | 39217 | 678.80 | 12.17 |
| 201103-201411 | TEPCO | 1111 | 805 | 484 | 579 | 621 | 325 | 287 | 117 | 26 | 1 | 6 | 4362 | 678.80 | 23.22 |
| | Contractors | 10940 | 8558 | 4587 | 4864 | 5238 | 1220 | 169 | 20 | 2 | 2 | 0 | 35600 | 238.42 | 10.79 |
| | Total | 12051 | 9363 | 5071 | 5443 | 5859 | 1545 | 456 | 137 | 28 | 3 | 6 | 39962 | 678.80 | 12.15 |
| 201103-201412 | TEPCO | 1132 | 805 | 489 | 581 | 617 | 328 | 290 | 117 | 26 | 1 | 6 | 4392 | 678.80 | 23.12 |
| | Contractors | 11077 | 8740 | 4672 | 4954 | 5353 | 1258 | 175 | 20 | 2 | 2 | 0 | 36253 | 238.42 | 10.85 |
| | Total | 12209 | 9545 | 5161 | 5535 | 5970 | 1586 | 465 | 137 | 28 | 3 | 6 | 40645 | 678.80 | 12.17 |
| 201103-201501 | TEPCO | 1136 | 811 | 494 | 581 | 617 | 330 | 290 | 117 | 26 | 1 | 6 | 4409 | 678.80 | 23.09 |
| | Contractors | 11319 | 8884 | 4722 | 4985 | 5440 | 1286 | 176 | 20 | 2 | 2 | 0 | 36836 | 238.42 | 10.83 |
| | Total | 12455 | 9695 | 5216 | 5566 | 6057 | 1616 | 466 | 137 | 28 | 3 | 6 | 41245 | 678.80 | 12.14 |
| 201103-201502 | TEPCO | 1128 | 820 | 494 | 590 | 619 | 329 | 292 | 117 | 26 | 1 | 6 | 4422 | 678.80 | 23.11 |
| | Contractors | 11449 | 9159 | 4927 | 5042 | 5561 | 1324 | 182 | 20 | 2 | 2 | 0 | 37668 | 238.42 | 10.85 |
| | Total | 12577 | 9979 | 5421 | 5632 | 6180 | 1653 | 474 | 137 | 28 | 3 | 6 | 42090 | 678.80 | 12.14 |
| 201103-201503 | TEPCO | 1117 | 828 | 494 | 596 | 620 | 331 | 293 | 117 | 26 | 1 | 6 | 4429 | 678.80 | 23.16 |
| | Contractors | 11470 | 9057 | 5011 | 5380 | 5701 | 1363 | 196 | 20 | 2 | 2 | 0 | 38202 | 238.42 | 11.05 |
| | Total | 12587 | 9885 | 5505 | 5976 | 6321 | 1694 | 489 | 137 | 28 | 3 | 6 | 42631 | 678.80 | 12.31 |
| 201103-201504 | TEPCO | 1146 | 837 | 496 | 597 | 621 | 333 | 295 | 117 | 26 | 1 | 6 | 4475 | 678.80 | 22.99 |
| | Contractors | 11624 | 9076 | 5083 | 5451 | 5852 | 1400 | 204 | 20 | 2 | 2 | 0 | 38714 | 238.42 | 11.16 |
| | Total | 12770 | 9913 | 5579 | 6048 | 6473 | 1733 | 499 | 137 | 28 | 3 | 6 | 43189 | 678.80 | 12.38 |
| 201103-201505 | TEPCO | 1149 | 840 | 492 | 603 | 620 | 333 | 298 | 117 | 26 | 1 | 6 | 4485 | 678.80 | 22.99 |
| | Contractors | 11788 | 9142 | 5093 | 5464 | 5966 | 1433 | 206 | 20 | 2 | 2 | 0 | 39116 | 238.42 | 11.21 |
| | Total | 12937 | 9982 | 5585 | 6067 | 6586 | 1766 | 504 | 137 | 28 | 3 | 6 | 43601 | 678.80 | 12.42 |
| 201103-201506 | TEPCO | 1147 | 836 | 498 | 601 | 627 | 331 | 301 | 117 | 26 | 1 | 6 | 4491 | 678.80 | 23.01 |
| | Contractors | 11924 | 9238 | 5134 | 5499 | 6021 | 1476 | 214 | 20 | 2 | 2 | 0 | 39530 | 238.42 | 11.25 |
| | Total | 13071 | 10074 | 5632 | 6100 | 6648 | 1807 | 515 | 137 | 28 | 3 | 6 | 44021 | 678.80 | 12.45 |

Note)

*The values of the exposure dose and the number of the workers in the table above are subject to change, because there are times when APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Main Anti-earthquake Building) need to be updated in the table after the publication of the data.

*The record months of the internal exposure dose of workers in the data above can be changed, even if the evaluation values of their internal exposure dose have not changed, when their "inhalation exposure days" (the days when they inhaled radioactive materials) are reviewed. Regarding the data this time, the record months of some workers have been changed.