Fukushima Daiichi Nuclear Power Station Unit2 Parameters of Temperature



※ "Vessel bottom above skirt jot (TE-2-3-69F3)" has been deleted since it is valuated as "Failure" by the reliability evaluation of the thermometer.