## Results of the radioactive material analysis related to the leaked water from the pipeline connecting from Desalination System (Reverse Osmosis Membrane) to Concentrated Water Storage Tank in Fukushima Daiichi Nuclear Power Station

## **Unit 1 to 4 side of South Discharge Channel**

[Sampling Point] Unit 1 to 4 side of South Discharge Channel, Fukushima Daiichi NPS

[Sampling Date and Time] On October 7, 2012 (Sunday)

No sampling due to the bad weather.

## [Results]

Nuclide	Concentration of Radioactive Material (Bq/cm³)	Detection Limit (Bq/cm³)	Half-life Period
I-131	-	-	-
Cs-134	-	-	-
Cs-137	-	-	-
Sb-125	-	-	-
All β	-	-	-

This shows only detected  $\gamma$  nuclides.