

5. Analysis Results of Groudwater Obtained around the H4 Area at Fukushima Daiichi Nuclear Power Station

Unit: Bq/L, "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

