Gas Sampling Results of Unit 3 PCV Gas Control System Conducted at Fukushima Daiichi Nuclear Power Station (Data summarized on July 10)

Place of Sampling	Exit of Unit 3 PCV Gas Control System			
Type of Sampling	Particulate Filter		Charcoal Filter	
Time of Sampling	Jul 4, 2013 9:02 AM - 9:12 AM		Jul 4, 2013 9:12 AM - 9:42 AM	
Detected Nuclides (Half-life)	Density of Sample (Bq/cm³)	Detection Limit Density (Bq/cm ³)	Density of Sample (Bq/cm³)	Detection Limit Density (Bq/cm ³)
I-131 (Approx. 8 days)	ND	9.6E-07	ND	5.8E-07
Cs-134 (Approx. 2 years)	ND	2.1E-06	ND	1.2E-06
Cs-137 (Approx. 30 years)	ND	2.9E-06	ND	1.7E-06

^{*} O.OE-O is the same as O.O x 10^{-} O

^{* &}quot;ND" indicates that the measurement result is below the detection limit.

This sampling is intended for the nuclides analysis result of cesium and iodine.