

6. Analysis Results Obtained in Drainage Channels around the H4 Area in Fukushima Daiichi Nuclear Power Station

Unit: Bq/L, "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* The latest amounts from "Sampling Results Regarding the Water Leak at the Tanks in the H4 area in Fukushima Daiichi Nuclear Power Station (South Water Outlet, Drainage Channel)" are provided in this report.

