

5. Analysis Results of Groudwater Obtained around the H4 Area at Fukushima Daiichi Nuclear Power Station

Unit: Bq/L "ND"s below indicate that the measurement results are below the detection limits, and the detection limit of each nuclide is provided in parentheses.

