

## 2. Analysis Results of Seawater Obtained around Fukushima Daiichi NPS (Inside of the Port of Fukushima Daiichi NPS)

Unit: Bq/L "ND"s below indicate that the measurement results are below the detection limits, and the detection limit of each nuclide is provided in parentheses.

\* The figures provided below for each point are the latest ones of "Detailed Analysis Results in the Port, around the Discharge Channel and the Bank Protection of Fukushima Daiichi NPS".

