

## Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

### <Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND ( 5.9E-01 )	ND ( 8.2E-01 )	Treated water tank	Jul 17, 2014	3:25 PM
Cs-137	ND ( 5.8E-01 )	ND ( 9.1E-01 )			
Gross β	ND ( 8.3E-01 )	ND ( 9.3E-01 )			
Tritium	1.4E+02	1.3E+02	Receiving tank	Jul 15, 2014	11:30 AM
Notification density rate*	0.05	0.06			

\* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

\* Analysis of tritium is performed at Environment Management Building.