

## Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

### <Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND ( 6.5E-01 )	/	Treated water tank	Aug 30, 2014	5:10 PM
Cs-137	ND ( 5.8E-01 )				
Gross β	ND ( 4.4E+00 )				
Tritium	6.8E+02		Receiving tank	Aug 28, 2014	1:50 PM
Notification density rate*	0.18				

\* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

\* Analysis of tritium is performed at Environment Management Building.