



November 30, 2015
Tokyo Electric Power Company


Air Dose Rates inside the Buildings


Sampling Period



Unit 3: from April 1, 2015 to September 30, 2015




































Fukushima Daiichi NPS

Units 3 and 4 Service Building 1st Basement Floor


[mSv/h]



Fukushima Daiichi NPS

Units 3 and 4 Service Building Semi-Basement Floor


[mSv/h]



Fukushima Daiichi NPS

Units 3 and 4 Service Building 1st Floor

[mSv/h]



Fukushima Daiichi NPS

Units 3 and 4 Service Building 2nd Floor

[mSv/h]

