






Completion of Reliability Improvement Work for Units 1-2 Accumulated Water Transfer Pipeline at Fukushima Daiichi Nuclear Power Station



New Units 1-2 Accumulated water transfer pipeline (replaced with polyethylene pipe)

-  Transfer pipeline which has been replaced with polyethylene pipe
-  Transfer pipeline where pressure hose is used
-  Former Units 1-2 transfer pipeline (pressure hose)
-  Buildings where the accumulated water level changes in relation to one another