


Debris Removal from the Upper Part of Unit 3 Reactor Building at Fukushima Daiichi Nuclear Power Station

< Reference >
February 4, 2013
Tokyo Electric Power Company

The steel truss in the upper part of the spent fuel pool will be removed in early February. The steel beam interfering with the steel truss removal has been performed based on investigation results and completed on February 1.



Interfering debris (Before removal)




Interfering debris (After removal)

* Timing of debris removal is subject to change depending on the work progress.

Debris Removal from the Upper Part of Unit 3 Reactor Building at Fukushima Daiichi Nuclear Power Station


After removing the steel truss debris, protection will be installed on the spent fuel pool and debris removal from the upper part of the operation floor will be started.



Debris removal from the upper part of the operation floor



Full view of the Northwest side
(Photo taken on January 29, 2013)



Protection installed on the spent fuel pool