

A Foreign Material Found and Collected in Unit 6 Spent Fuel Pool at Fukushima Daiichi NPS

<Reference>
May 29, 2013

Tokyo Electric Power Company

<Outline>

- Since May 20, inspection of the spent fuel rack installed in Unit 6 spent fuel pool has been started.
- At around 3:10 PM on May 23, a TEPCO employee, who was conducting inspection of a spent fuel rack at the Unit 6 spent fuel pool, found a foreign object (something like an eye nut*) at the east-side bottom of the spent fuel pool while checking a video tape having the rack inspection recorded.
- At 4:50 PM on May 28, the foreign object (one eye nut) was collected.



<Condition of the foreign material in the spent fuel pool>
Photo taken on May 23, 2013



<The collected foreign material (an eye nut)>
Photo taken on May 28, 2013



<The collected foreign material (an eye nut)>
Photo taken on May 28, 2013