



<Reference>
September 29, 2013
Tokyo Electric Power Company

Flow Rate Decrease of Slurry Transfer Pump of Multi-nuclide Removal Equipment System C

System diagram of the Entire Multi-nuclide Removal Equipment (ALPS)



Results of internal inspection of the batch treatment tank 2C



Results of internal inspection of the batch treatment tank 2C



One of the rubber pads for ladder
found detached
(found near the drain hole)



The other one of rubber pad for
ladder found remaining attached
at its original location (measured
for size after being released from
fixation with tape)