

- July 30, 2015 transfer of accumulated water in trench completed.
- Filling up Shaft A and Shaft C to the ground level completed.
- Filling up the main part of Shaft D completed. The top part is connected to the turbine building so filling up is to be continued as the water level of the accumulated water is lowered in the building.
- Filling up of Shaft B completed today (August 27).



Shaft A



Unit 3 Seawater piping trench schematic cross-sectioned view





Filling up Shaft at Unit 3 Seawater piping trench

August 27 Filling up Shaft B





Photos taken by Tokyo Electric Power Company Photos taken on August 27, 2015

