

# Result of radiation dose survey at reactor building of Unit 3 In Fukushima Daiichi Nuclear Power Station



Date of survey : June 9, 2011 11 : 47 am ~ 0:14 pm  
 Number of Workers : Total 9 ( TEPCO 5, Partner Company 4 )  
 Dose : 5.88 ~ 7.96mSv  
 Area : South side and west side of first floor, reactor building of Unit 3



Exterior appearance of instrument panel ( area )



Ladder ( area )



: Area of dust sampling

**Unit of the measurement : mSv/h**



Upper section of Nearby Instrumentation rack ( area )



Nearby Instrumentation rack ( area )