The repaired part for chemical leakage of water treatment system

(coagulation settling facility)



<u>Hose Connection (before repair)</u>



Hose Connection (after repair)

Photo by: Tokyo Electric Power Company

Date: July 12, 2011