
July 14, 2011



Outline structure of damaged part on chemical injection line for coagulation settling equipment