

< Reference >
September 17,2011
Tokyo Electric Power Company

Fukushima Daiichi Nuclear
Power Plant Photo Collection

Date : September 15-16, 2011
Source : Tokyo Electric Power Company

List

< Unit 1 >

Reactor building cover from northern side

Sep 15, 2011

Reactor building cover from northern side

Sep 15, 2011

View from large crane around a reactor building

Sep 15, 2011

Southern direction (Unit 3 & 4) from Unit 1

Sep 15, 2011

< Unit 2 >

Overview of a reactor building from western hilltop

Sep 15, 2011

< Unit 3 >

Overview of a reactor building from western hilltop

Sep 15, 2011

Rubble collection around southwest of a reactor building

Sep 16, 2011

Rubble collection preparation of a reactor building

~ north direction (Unit 1&2) from Unit 3 ~

Sep 15, 2011

< Unit 4 >

Overview of a reactor building from western hilltop

Sep 15, 2011

Rubble collection preparation of a reactor building

~ north direction from Unit 4 ~

Sep 15, 2011

< Unit 5,6 >

Overview of a reactor building from southwest side

Sep 15, 2011

Maintenance work at port and harbors from Unit 6
seaside yard

Sep 15, 2011

< Tank area >

RO concentrated water storage tank (H 1 east area)

Sep 15, 2011

RO concentrated water storage tank (H 1 area)

Sep 15, 2011

< Centralized Radiation Waste Treatment Facility >

Overview

Sep 16, 2011

* All photos by TEPCO employee


Unit 1



Reactor building cover from northern side
Sep 15, 2011



Reactor building cover from northern side
Sep 15, 2011



View from large crane around a reactor building
Sep 15, 2011



Southern direction (Unit 3 & 4) from Unit 1
Sep 15, 2011

Unit 2



Overview of a reactor building from western hilltop
Sep 15, 2011

Unit 3



Overview of a reactor building from western hilltop
Sep 15, 2011



Rubble collection around southwest of a reactor building
Sep 16, 2011



Rubble collection preparation of a reactor building
~ north direction (Unit 1&2) from Unit 3 ~
Sep 15, 2011

Unit 4



Overview of a reactor building from western hilltop
Sep 15, 2011



Rubble collection preparation of a reactor building
~ north direction from Unit 4 ~
Sep 15, 2011

Unit 5 & 6



Overview of a reactor building from southwest side
Sep 15, 2011



Maintenance work at port and harbors from
Unit 6 seaside yard Sep 15, 2011

Tank area



RO concentrated water storage tank (H1 east area)
Sep 15, 2011



RO concentrated water storage tank (H1 area)
Sep 15, 2011

Centralized Radiation Waste Treatment Facility



Overview
Sep 16, 2011

Location Map of Fukushima Daiichi Nuclear Power Plant

