



Situation of inside of Unit 2 Reactor Building, Fukushima Daiichi Nuclear Power Station

September 24, 2011
Tokyo Electric Power Company



The movie was recorded when dust sampling survey was conducted at blow-out panel opening of Unit 2 R/B on September 17, 2011. The location of the camera is approximate one. Dot lines roughly show the angle of view of the camera.



Layout drawing of 5th floor of Unit 2 R/B, Fukushima Daiichi

Photographer : Tokyo Electric Power Company
Date : September 17, 2011