


Situation of Upper Part of Unit 3 Reactor Building, Fukushima Daiichi Nuclear Power Station

September 24, 2011
Tokyo Electric Power Company



Layout drawing of 5th floor of Unit 3 reactor building in Fukushima Daiichi Nuclear Power Station

- Movie was recorded when dust sampling survey was conducted at upper part of reactor building of Unit 3, on August 24, 2011
- The location of the camera is approximate one



Photographer: Tokyo Electric Power Company
Recording date: August 24, 2011