


Situation of Upper Part of Unit 2 Reactor Building, Fukushima Daiichi Nuclear Power Station

October 8, 2011
Tokyo Electric Power Company



Layout drawing of 5th floor of Unit 2 reactor building in Fukushima Daiichi Nuclear Power Station

- Movie was recorded from blow-out panel opening when dust sampling survey was conducted at upper part of reactor building of Unit 2, on October 5, 2011
- The location of the camera is approximate one
- Dotted line indicates the approximate range to be recorded by camera.



Photographer: Tokyo Electric Power Company
Recording date: October 5, 2011