

November 7th, 2011
Tokyo Electric Power Company

Installation Status of Radioactive Material Removal Facility at the Unit 2's Spent Fuel Pool of Fukushima Daiichi Nuclear Power Station



Cesium Adsorption Tower inside the facility.



Cesium Adsorption Tower Unit

Photo taken on: November 6, 2011

Taken by: Tokyo Electric Power Company



Valve Unit inside

Valve Unit

Photo taken on : November 6, 2011

Taken by : Tokyo Electric Power Company