


[Reference]

Leakage from evaporative condensation apparatus

December 4, 2011
Tokyo Electric Power Company



Evaporative condensation apparatus (indoor)



Status of leakage (part 1)



Status of leakage (part 2)



Gutter close to evaporative condensation apparatus
Photos taken on December 4, 2011
Shooting by TEPCO