


Accumulated water in the trench between Process Main Building and Miscellaneous Solid Waste Volume Reduction Treatment Building (High Temperature Incinerator Building) in the Centralized Radiation Waste Treatment Facility at Fukushima Daiichi Nuclear Power Station



【photo 】 look up view cable duct

Date : December 18
Photo : Tokyo Electric Power Company



【photo 】 Accumulated water in the trench

Date : December 18
Photo : Tokyo Electric Power Company