

Status of the water leakage at concentrated water storage tank area of water desalinations (reverse osmosis membrane) in Fukushima Daiichi Nuclear Power Station



Photo taken on March 26, 2012
by TEPCO



Photo taken on March 26, 2012
by TEPCO



Photo taken on March 26, 2012
by TEPCO



Photo taken on March 26, 2012
by TEPCO



Photo taken on March 26, 2012
by TEPCO



Photo taken on March 26, 2012
by TEPCO