


The Accumulated Water Found at Unit 2 Radioactive Waste Underground Storage Facility (Newly Established) at Fukushima Daiichi Nuclear Power Station





1. Location where water flow was confirmed on Unit 2 Offgas Pipe Duct



2. North Wall of the Spent Resin Storage Tank Room