



Fukushima Daiichi Nuclear Power Station Unit 3 Reactor Building Operating Floor Area Investigation

< Reference >
July 11, 2012
Tokyo Electric Power Company




Operating Floor



Northwest part of the Operating Floor



East part of the Operating Floor



* Enlarged image of the equipment hatch



Fourth floor (Photo taken from the equipment hatch)



Third floor (Photo taken from the equipment hatch)