



Damage of Unit 2 PCV Gas Control System Duct at Fukushima Daiichi Nuclear Power Station

< Reference >
September 10, 2012
Tokyo Electric Power Company



Photos taken on September 9, 2012 by TEPCO