


## Investigation of the Inside of Unit 3 Spent Fuel Pool Using an Underwater Camera at Fukushima Daiichi Nuclear Power Station

### Underwater camera investigation on September 25

- 17 workers involved
- From around 7:00 AM to around 11:10 AM



Debris on the fuel storage rack investigated on September 24



Steel beam investigated on September 24

\* Photos and are captured images of the underwater camera video recorded on September 24.


Steel beam investigated on September 24



Steel beam investigated on September 25



Steel beam investigated on September 25



[Legend]

: Fuel storage rack

: Areas investigated on September 24 and 25

: Area to be investigated on September 26

\* Photos and are captured images of the underwater camera video recorded on September 25.