

## Analysis Result of the Accumulated Water in Unit 1 PCV at Fukushima Daiichi Nuclear Power Station

Analysis item		Accumulated water in Unit 1 PCV (Sampled on October 12, 2012)	Accumulated water in the northeast triangle corner in Unit 1 Reactor Building (Sampled on September 20, 2012)
pH		7.2	-
Conductivity [ $\mu$ S/cm]		88	-
Chloride concentration [ppm]		19	200
radioactivity density [Bq/cm <sup>3</sup> ]	Cs134	1.9E+04	4.1E+04
	Cs137	3.5E+04	7.4E+04
	I-131	ND	ND