



Smoke Coming out from Damaged Power Cable at Fukushima Daiichi Nuclear Power Station

[Location where the incident occurred (Power station map)]



[Location where the incident occurred (Power supply system)]



[Location where smoke came out (Photo 1)]



Photo taken on November 2, 2012 by TEPCO

[Location where smoke came out (Photo 2)]



Photo taken on November 2, 2012 by TEPCO