

Investigation of the Inside of Unit 4 Suppression Chamber at Fukushima Daini Nuclear Power Station

< Reference >

November 21, 2012

Tokyo Electric Power Company



The substances indicated by red circles are paint peel-off.

The brownish powdery accumulation is rust inside the pipe
which came off.

Photo taken on November 14, 2012 by TEPCO