

Result of Plutonium measurement analysis on Sub-drain water
in Fukushima Daiichi nuclear power plant

1. sampling location:

Fukushima Daiichi nuclear power station, sub-drain of Unit 1 and 2

2. institution conducted analysis:

JCAC

3. result of the analysis

Sample	Sampling date	Pu-238	Pu-239, Pu-240
Unit 1 sub-drain	5/18	N.D.	N.D.
Unit 2 sub-drain		N.D.	N.D.

4. evaluation:

Pu-238, Pu-239, and Pu-240 were not detected from the samples analyzed.

END